



# Technical Service Bulletin

No.A206-08

11 July 2005

<b>Subject/Concern:</b>	Revised Parking Brake Cable Adjustment
-------------------------	--

<b>Models:</b>		
X-TYPE		VIN-range: C00294 Onwards

**Markets:** All**Section:** 206-05

<b>Summary:</b>
This bulletin has been issued for information only, to inform Authorized Repairers that there has been a change in the parking brake cable adjustment measurement. The gap between the parking brake caliper lever and the parking brake caliper lever stop previously 0.1mm to a maximum of 1mm, has now changed to 0.1mm to a maximum of 1.5mm.
<b>Cause:</b> Incorrect parking brake cable adjustment.
<b>Action:</b> To carry out the new parking brake cable adjustment measurement, follow the Service Instruction outlined below.

<b>Parts Required:</b>		
<b>Description</b>	<b>Part Number</b>	<b>Quantity</b>
N/A		N/A

<b>Labour Time:</b>		
<b>Operation Description</b>	<b>Operation No.</b>	<b>Time</b>
N/A		N/A

<b>Repair/Claim Coding:</b>	
<b>Causal Part:</b>	N/A
<b>ACES Condition Code:</b>	N/A
<b>Defect Code:</b>	N/A

## Service Instruction

- 1 . Parking brake cable adjustment (see Global Technical Reference GTR Workshop Manual, section: 206-05).

© 2005 Jaguar