



Technical Service Bulletin

No.A211-06

18 May 2005

Subject/Concern:	New Workshop Procedure to Remove/Install the Power Steering Pump
-------------------------	--

Models:		
X-TYPE	Diesel Only	Diesel Only VIN-range: D55322 Onwards

Markets: All

Section: 211-02

Summary:
This bulletin has been issued for information only, to inform Authorized Repairers of a change in the workshop procedure to remove/install the power steering pump.
<p>Cause: The current workshop procedure removes the Exhaust Gas Recirculation (EGR) transfer pipe. The new method leaves the EGR transfer pipe in place.</p> <p>Action: To remove/install the power steering pump to the new workshop method, follow the Service Instruction referred to below.</p>

Parts Required:		
Description	Part Number	Quantity
N/A		N/A

NOTE: Repair procedures are under constant review, and therefore times are subject to change; those quoted here must be taken as guidance only. Always refer to DDW to obtain the latest repair time.

NOTE: Old Labor Time - Power steering pump - Renew - 57 20 14 - 1.9 hours

Labour Time:		
Operation Description	Operation No.	Time
Power steering pump - Renew	57 20 14	1.7 hours

Repair/Claim Coding:	
Causal Part:	N/A
ACES Condition Code:	N/A
Defect Code:	N/A

Service Instruction

1. Remove/install the power steering pump (see Global Technical Reference GTR Workshop Manual, section 211-02).

©2005 Jaguar