



# Technical Service Bulletin

No.A206-11  
29 March 2006

<b>Subject/Concern:</b>	Anti-Lock Brake System (ABS) Module Replacement
-------------------------	---

<b>Models:</b>		
X-TYPE	All vehicles without Interactive Vehicle Dynamics (IVD)	All vehicles without Interactive Vehicle Dynamics (IVD) VIN-range: C00294 Onwards

**Markets:** All

**Section:** 206-09

<b>Summary:</b>
This bulletin has been issued for information only, to inform Authorized Repairers that the ABS module is now being serviced separately from the hydraulic control unit.
<b>Cause:</b> Cost reduction.
<b>Action:</b> To install a new ABS module, follow the Service Instruction outlined below.

<b>Parts Required:</b>		
<b>Description</b>	<b>Part Number</b>	<b>Quantity</b>
ABS module - AWD	C2S 42661	1
ABS module - FWD	C2S 42662	1

<b>Labour Time:</b>		
<b>Operation Description</b>	<b>Operation No.</b>	<b>Time</b>
ABS Module - Renew	70.60.02	0.4 hours

<b>Repair/Claim Coding:</b>	
<b>Causal Part:</b>	C2S 42662 or C2S 42661
<b>ACES Condition Code:</b>	N/A
<b>Defect Code:</b>	

## Service Instruction

1. ABS Module - Renew (see Global Technical Reference GTR Workshop Manual, section: 206-09).

©2006 Jaguar