



Technical Service Bulletin

No.A307-05
21 March 2006

Subject/Concern:	Automatic Transmission Hand Selector Lever Replacement
-------------------------	--

Models:	
X-TYPE	VIN-range: D15361 Onwards

Markets: All

Section: 307-05

Summary:
This bulletin has been issued for information only, to inform Authorized Repairers that the automatic transmission hand selector lever is now being serviced without the lower mounting bracket.
Cause: Cost reduction.
Action: To install a new hand selector lever, follow the Service Instruction outlined below.

Parts Required:		
Description	Part Number	Quantity
Hand selector lever	C2S 36881	1

Labour Time:		
Operation Description	Operation No.	Time
Hand selector lever - Renew	44.15.03	1.1 hours

Repair/Claim Coding:	
Causal Part:	C2S 36881
ACES Condition Code:	N/A
Defect Code:	

Service Instruction

1. Hand selector lever - Renew (see Global Technical Reference GTR Workshop Manual, section: 307-05).

©2006 Jaguar