



Technical Service Bulletin

No.A308-11
01 May 2006

Subject/Concern:	Rattle From Clutch on Idle or Shift Rattle on Acceleration
-------------------------	--

Models:

X-TYPE	2.0L, 2.5L, 3.0L Gasoline V6 Only	2.0L, 2.5L, 3.0L Gasoline V6 Only	VIN-range: C00298 Onwards
--------	-----------------------------------	-----------------------------------	---------------------------

Markets: All

Section: 308-01

Summary:

This bulletin addresses customer concerns of a rattle from the clutch area at idle, or shift rattle on acceleration.

Cause: No anti-rattle feature on current clutch disc.

Action: On a customer complaint basis only, install a new clutch disc (part number listed below).
Follow the Service Instruction outlined below.

Parts Required:

Description	Part Number	Quantity
Clutch disc	C2S 33393	1

Labour Time:

Operation Description	Operation No.	Time
Install new clutch disc - 2.0L	33.10.01	6.6 hours
Install new clutch disc - 2.5L and 3.0L	33.10.01	8.6 hours

Repair/Claim Coding:

Causal Part:	C2S 33393
ACES Condition Code:	N/A
Defect Code:	

Service Instruction

1. Install new clutch disc (see Global Technical Reference GTR Workshop Manual, section 308-01).

©2006 Jaguar