



# Technical Service Bulletin

No.A308-04v2  
17 October 2005

Reissue

Please replace the previous edition of this bulletin.

This bulletin supersedes TSB A308-04/2004 dated 10 September, which should either be destroyed or clearly marked to show it is no longer valid (e.g. with a line across the page).

<b>Subject/Concern:</b>	Transmission Whine (Noise)
-------------------------	----------------------------

<b>Models:</b>		
X-TYPE		VIN-range: C00294-E50882

**Markets:** All

**Section:** 308-06

<b>Summary:</b>
This bulletin addresses customer concerns of a transmission whine (noise) emanating from the transmission, and the whine (noise) being transmitted along the gearshift cable into the cabin.
<b>Cause:</b> Gearshift cable.
<b>NOTE:</b> This Technical Bulletin MUST be carried out and the vehicle re-tested prior to the transmission being replaced.
<b>Action:</b> Should a customer express concern, a modified gearshift cable must be installed. Follow the workshop procedure outlined below.

<b>Parts Required:</b>		
<b>Description</b>	<b>Part Number</b>	<b>Quantity</b>
Gearshift cable	C2S 33004	1

<b>Labour Time:</b>		
<b>Operation Description</b>	<b>Operation No.</b>	<b>Time</b>
Install new gearshift cable	37 16 45	1.2 hours

<b>Repair/Claim Coding:</b>	
<b>Causal Part:</b>	C2S 33004
<b>ACES Condition Code:</b>	N/A
<b>Defect Code:</b>	

## Service Instruction

1. Install a new gearshift cable (see Global Technical Reference GTR Workshop Manual, section: 308-06).

©2005 Jaguar