



Technical Service Bulletin

No.A308-05
19 January 2005

Subject/Concern:	New Manual Transmission/Transaxle Gearshift Linkage Assembly Remove/Install Procedure
-------------------------	---

Models:		
X-TYPE	Manual	Manual VIN-range: C00249 Onwards

Markets: All

Section: 308-03

Summary:
This Technical Bulletin has been issued for information only, to inform Authorized Repairers of a change in the workshop procedure to remove/install the manual transmission/transaxle gearshift linkage assembly.
To carry out the new procedure, follow the Service Instruction referred to below.

Parts Required:		
Description	Part Number	Quantity
N/A		N/A

Labour Time:		
Operation Description	Operation No.	Time
Gearshift linkage assembly - Renew	37 16 46	2 hours

Repair/Claim Coding:	
Causal Part:	N/A
ACES Condition Code:	N/A
Defect Code:	N/A

Service Instruction

- 1 . To remove and install the manual transmission/transaxle gearshift linkage assembly (see Global Technical Reference GTR Workshop Manual, section 308-03).

© 2005 Jaguar