



Technical Service Bulletin

No.JTB00079
15 January 2008

Subject/Concern:	Revised Procedure - Automatic Transmission Transaxle Renew
-------------------------	--

Models:		
X-TYPE	V6 2.5L & 3.0L	V6 2.5L & 3.0L VIN-range: C00344 Onwards

Markets: All

Section: 307-01

Summary:
This Bulletin has been released for information only. The renewal procedure for the automatic transmission transaxle has changed.
Cause: The procedure has been modified so that the driveshaft is not completely removed, but disconnected at the front joint and secured to the front exhaust hanger.
Action: When removing/installing a transaxle, follow the Service Instruction referred to below.

NOTE: Old labor time - 9.5 hours.

Labour Time:		
Operation Description	Operation No.	Time
Remove and Install Automatic Transmission Transaxle	44.20.01	8.5 hours

Service Instruction

- 1 . Install a new transaxle following the workshop procedure outlined in the Workshop Manual (GTR) Section 307-01.

©2008 Jaguar