



Technical Service Bulletin

No.A308-08
15 February 2006

Subject/Concern:	New Workshop Procedure to Remove/install the Transfer Case
-------------------------	--

Models:

X-TYPE	MIN-range: C00294 Onwards
--------	---------------------------

Markets: All

Section: 308-07

Summary:

This bulletin has been issued for information only, to inform Authorized Repairers of a change in the workshop procedure to remove/install the transfer case.

NOTE: Associated repairs that require the new workshop procedure will also change.

Cause: The current workshop procedure calls for removal of the front subframe. The new method leaves the front subframe in place.

Action: To remove/install the transfer case to the new workshop procedure, follow the Service Instruction referred to below.

NOTE: Old Labor Time - Transfer Box Assembly - Renew - 46.10.01 - 5.5 hours

Labour Time:

Operation Description	Operation No.	Time
Transfer Box Assembly - Renew - Manual Transmission	46.10.01	3.9 hours
Transfer Box Assembly - Renew - Automatic Transmission	46.10.01	4.9 hours

Service Instruction

- 1 . Transfer Box Assembly - Renew (see Global Technical Reference GTR Workshop Manual, section: 308-07).

©2006 Jaguar