



Technical Service Bulletin

No.A206-09
24 October 2005

Subject/Concern:	Warranty Brake Disc Renewal - Policy Change
-------------------------	---

Models:		
X-TYPE		VIN-range: E67744 Onwards

Markets: All

Section: 206-00

Summary:
<p>The current policy of replacing brake discs in pairs on the same axle for low time in service has now been rescinded. The policy for replacing brake discs has been revised and is detailed below.</p> <p>During the warranty life of the vehicle the failed part only shall be changed using the following criteria:</p> <ul style="list-style-type: none">• From PDI, the vehicle has completed less than 1000 miles (1600 kilometers).• Only one brake disc across an axle exhibits the fault.• The part number of the replacement disc is identical to that being removed. <p>NOTE: For any other brake disc replacement outside the criteria outlined above, the current policy of replacing an axle set remains.</p>

Parts Required:		
Description	Part Number	Quantity
Front brake disc	C2S 42667S	1
Rear brake disc	C2S 42668S	1

Service Instruction

Effective immediately, observe the above points when replacing brake discs under warranty.

1. **NOTE:** De-glaze and re-install the front brake pads.

Install brake disc (see Global Technical Reference GTR Workshop Manual, section: 206-03/04).

© 2005 Jaguar