



Technical Service Bulletin

No.JTB00080
15 January 2008

Subject/Concern:	Revised procedure - Manual Transmission Transaxle Renew
-------------------------	---

Models:		
X-TYPE	V6 2.5L & 3.0L	V6 2.5L & 3.0L VIN-range: C00344 Onwards

Markets: All

Section: 308-03

Summary:
This Bulletin has been released for information only. The renewal procedure for the manual transmission transaxle has changed.
Cause: The procedure has been modified so that the driveshaft is not completely removed, but disconnected at the front joint and secured to the front exhaust hanger.
Action: When removing/installing a transaxle, follow the Service Instruction referred to below.

NOTE: Old labor times: Transaxle - 8.8 hours; Clutch - 8.6 hours.

Labour Time:		
Operation Description	Operation No.	Time
Remove and Install Manual Transmission Transaxle	37.20.01	7.9 hours
Remove and Install Clutch Disc and Pressure Plate	33 10 01	7.6 hours

Service Instruction

- 1 . Install a new transaxle following the workshop procedure outlined in the Workshop Manual (GTR) Section 308-03.

©2008 Jaguar